

## State of Utah

# Department of Natural Resources

MICHAEL R. STYLER
Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

 $\begin{array}{c} {\rm JON~M.~HUNTSMAN,~JR.} \\ {\rm \it Governor} \end{array}$ 

GARY R. HERBERT Lieutenant Governor

Representative	es Present During the Inspection:	
Company	Kit Pappas Environmental Coordinator	
OGM	Karl Houskeeper Environmental Scientist III	

# **Inspection Report**

Permit Number:	C0070020		
Inspection Type:	PARTIAL		
Inspection Date:	Friday, November 18, 2005		
Start Date/Time:	11/18/2005 10:00:00 AM		
End Date/Time:	11/18/2005 1:00:00 PM		
Last Inspection:	Friday, October 21, 2005		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 45 Deg. F
InspectionID Report Number: 788

Accepted by: pgrubaug 11/28/2005

Permitee: HIDDEN SPLENDOR RESOURCES INC Operator: HIDDEN SPLENDOR RESOURCES INC

Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

## Current Acreages Mineral Ownership Types of Operations

1,998.99	<b>Total Permitted</b>	✓ Federal	Underground
9.50	Total Disturbed	☐ State	☐ Surface
	Phase I	☐ County	Loadout
	Phase II	<b>✓</b> Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

No violations.

Inspector's Signature Date Friday, November 18, 2005

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Friday, November 18, 2005

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		<b>✓</b>	
2.	Signs and Markers	<b>✓</b>		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>			
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>✓</b>			
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		<b>✓</b>	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	<b>✓</b>			
6.	Disposal of Excess Spoil, Fills, Benches		<b>✓</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments		<b>✓</b>		
8.	Noncoal Waste	<b>✓</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.k	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	✓		✓	

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Friday, November 18, 2005 Page 3 of 3

### 1. Permits, Change, Transfer, Renewal, Sale

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

No violations.

#### 2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, permit number, and MSHA number. The sign has been modified to include the new address and phone number.

#### 4.d Hydrologic Balance: Water Monitoring

Third and Fourth quarter 2005 water monitoring information is contained in the EDI website and are uploaded. Water monitoring is current.

### 22. Other

Verbal notification was given to the Division during the partial inspection that 1st West Mains from cross cut #40 inby will be permanently sealed in approximately two to three weeks. MSHA has determined that the area is unsafe for entry. The BLM has been notified and Steve Falk from BLM was underground at the Horizon Mine to evaluate the area during the DOGM partial inspection.